



### Recreational Water Inspection Report

<b>Establishment Information</b>	
Facility Name <b>SUPER 8 MOTEL</b>	Facility Type <b>Indoor Pool</b>
Facility ID # <b>MWAS-AUVQX5</b>	Facility Telephone # <b>608 781-8880</b>
Facility Address <b>1625 ROSE ST LA CROSSE , WI 54603</b>	
Licensee Name <b>GREAT RIVER OF LA CROSSE</b>	Licensee Address <b>1625 ROSE ST LA CROSSE , WI 54601</b>

<b>Pool Parameters</b>	
Free Available Chlorine/Bromine	4.2
Combined Chlorine	0.2
Oxidation Reduction Potential	
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.4
Alkalinity	240
Cyanuric Acid	
Temperature	81
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	80
Pressure Gauges Reading(s)	17
Turnover Rate	4.6

<b>Inspection Information</b>		
Inspection Type Routine	Inspection Date February 13, 2020	Total Time Spent

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

**Observed Violations**

**Total # 3**

**Observed Violations - 02 - Permit in public view.**

**OBSERVATION: (CORRECTED DURING INSPECTION):** The permit is not posted in a place visible to the public.

**CORRECTIVE ACTION(S):** Post the permit in public view.

**CODE CITATION:** ATCP 76.05 Permits. (7) PERMIT POSTING. A permit shall be posted in a place visible to the public. A permit may not be altered or defaced.

**Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.**

**OBSERVATION:** The total alkalinity is 240 ppm.

**CORRECTIVE ACTION(S):** Maintain the total alkalinity between 60 and 180 ppm. Correct By: 13-Feb-2020

**CODE CITATION:** ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (d) Alkalinity. The total alkalinity of pool water shall be maintained between 60 and 180 ppm as calcium carbonate unless it can be shown that another level of total alkalinity produces chemically balanced water based on calculations approved by the department.

**Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted**

**OBSERVATION:** The telephone dials the front desk automatically.

**CORRECTIVE ACTION(S):** Install an outside line and post the emergency numbers near the designated emergency phone. Correct By: 13-Feb-2020

**CODE CITATION:** ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

**Comments:**

[Reinspection for telephone and signage. Alkalinity will be checked also. Call with telephone schedule. Fee applies.](#)

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



**Jay Patel**



**Doug Schaefer**  
**(608) 785-9679**



### Recreational Water Inspection Report

<b>Establishment Information</b>	
Facility Name <b>SUPER 8 MOTEL</b>	Facility Type <b>Additional Indoor Pool</b>
Facility ID # <b>MWAS-AUVQYG</b>	Facility Telephone # <b>608 781-8880</b>
Facility Address <b>1625 ROSE ST LA CROSSE , WI 54603</b>	
Licensee Name <b>GREAT RIVER OF LA CROSSE</b>	Licensee Address <b>1625 ROSE ST LA CROSSE , WI 54601</b>

<b>Pool Parameters</b>	
Free Available Chlorine/Bromine	17
Combined Chlorine	1.6
Oxidation Reduction Potential	
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.6
Alkalinity	70
Cyanuric Acid	
Temperature	101
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	75
Pressure Gauges Reading(s)	18
Turnover Rate	0.4

<b>Inspection Information</b>		
Inspection Type Routine	Inspection Date February 13, 2020	Total Time Spent

**OPERATOR** - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

**Observed Violations**

**Total # 4**

**Observed Violations - 02 - Permit in public view.**

**OBSERVATION: (CORRECTED DURING INSPECTION):** The permit is not posted in a place visible to the public.

**CORRECTIVE ACTION(S):** Post the permit in public view.

**CODE CITATION:** ATCP 76.05 Permits. (7) PERMIT POSTING. A permit shall be posted in a place visible to the public. A permit may not be altered or defaced.

**Observed Violations - 14 - Disinfectant / feeders - proper concentration and chemical used. Gas chlorine.**

**OBSERVATION: (CORRECTED DURING INSPECTION):** The chlorine residual exceeded 10 ppm.

**CORRECTIVE ACTION(S):** Decchlor added and lowered chlorine to 9 ppm.

**CODE CITATION:** ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (f) Maximum chlorine residual. The maximum chlorine residual in any pool shall not exceed 10 ppm.

**Observed Violations - 31 - General maintenance, walls, ceilings. floors, hosing spectator area separated, maintained, no hazardous conditions, adequate lighting accessibility, solid waste, garbage storage and disposal.**

**REPEAT OBSERVATION:** Deck drain around hot tub is failing and not being maintained and repaired as necessary.

**CORRECTIVE ACTION(S):** Repair and maintain all equipment pursuant to ATCP 76.33(1)(e). Correct By: 13-Feb-2020

**CODE CITATION:** ATCP 76.33 Facility maintenance, repair and sanitation. (1) POOL AREA. (e) Equipment. Pool equipment, including equipment on the deck, shall be properly located and installed and maintained and repaired as necessary.

**Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted**

**OBSERVATION:** The telephone automatically dials the front desk.

**CORRECTIVE ACTION(S):** Install a direct line and post the emergency numbers near the designated emergency phone. Correct By: 13-Feb-2020

**CODE CITATION:** ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

**Comments:**

Reinspection for changing the phone and signage. Chlorine will be checked also. Call with telephone schedule. Reinspection fee applies.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



**Jay Patel**



**Doug Schaefer**  
**(608) 785-9679**