



Recreational Water Inspection Report

Establishment Information	
Facility Name LA CROSSE AREA FAMILY YMCA	Facility Type Indoor Pool
Facility ID # HSAT-7QXGFZ	Facility Telephone # 608 769-0384
Facility Address 1140 MAIN ST LA CROSSE , WI 54601	
Licensee Name LA CROSSE AREA FAMILY YMCA	Licensee Address 1140 MAIN ST LA CROSSE , WI 54601

Pool Parameters	
Free Available Chlorine/Bromine	1.8
Combined Chlorine	0.8
Oxidation Reduction Potential	
Disinfectant Type	Chlorine-Erosion
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.4
Alkalinity	140
Cyanuric Acid	
Temperature	85
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Routine	Inspection Date February 28, 2019	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 3

Observed Violations - 21 - Plumbing air-gaps, cross-connections, maintained, installed piping coded or labeled

OBSERVATION: The potable water supply line is too close to the receiving vessel.

CORRECTIVE ACTION(S): Install a proper air gap or a reduced pressure zone backflow assembly on the water supply line.
Correct By: 28-Feb-2019

CODE CITATION: ATCP 76.19 Water supply and temperature. (1) WATER SUPPLY PROTECTION. A minimum air-gap of 2 pipe diameters or 6 inches, whichever is less, shall exist between the potable water supply inlet and the overflow point of any pool, makeup tank, surge tank, solution tank, or slurry tank unless another department-approved backflow and backsiphonage prevention device is provided.

Observed Violations - 24 - Lifeguard staffing plans - if required - approved, verified, accurate, accessible, maintained and used.

OBSERVATION: The facility does not have a lifeguard and attendant staffing plan.

CORRECTIVE ACTION(S): Create a written plan pursuant to the requirements of ATCP 76.22 and submit it for approval.
Correct By: 15-Mar-2019

CODE CITATION: ATCP 76.22 Lifeguards and Attendants. (1) LIFEGUARD AND ATTENDANT STAFFING PLANS. (a) The owner or operator of a pool, including a whirlpool over 4 feet deep and a pool with a visual obstruction, and the owner or operator of a water attraction or water attraction complex shall submit a written, proposed lifeguard and attendant staffing plan to the department or the department's agent for approval. The owner or operator shall keep a copy of the plan at the pool. The plan shall include all of the following:

1. The square footage of the pool, water attraction, and water attraction complex as applicable.
2. The maximum and average patron load.
3. The hours of operation.
4. The location of each lifeguard station and each first aid station.
5. The number of lifeguards or attendants on duty pursuant to ATCP 76.23.
6. A diagram of the facility that indicates the placement of attendants, lifeguards, chairs and stations for both average and maximum patron capacity. The diagram shall include each obstruction.
7. A method of communication when 2 or more attendants or lifeguards are required for a water attraction.

Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted

OBSERVATION: The maintenance number and location are not posted near the designated emergency phone.

CORRECTIVE ACTION(S): Post the emergency numbers near the designated emergency phone. Correct By: 28-Feb-2019

CODE CITATION: ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

Comments:


Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Chris Swertfeger



Doug Schaefer
(608) 785-9679



Recreational Water Inspection Report

Establishment Information	
Facility Name LA CROSSE AREA FAMILY YMCA - WHIRLPOOL	Facility Type Additional Indoor Pool
Facility ID # HSAT-7QX7DG	Facility Telephone # 608 769-0384
Facility Address 1140 MAIN ST LA CROSSE , WI 54601	
Licensee Name LA CROSSE AREA YMCA	Licensee Address 1140 MAIN ST LA CROSSE , WI 54601

Pool Parameters	
Free Available Chlorine/Bromine	5.6
Combined Chlorine	1.4
Oxidation Reduction Potential	
Disinfectant Type	Chlorine-Erosion
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.4
Alkalinity	
Cyanuric Acid	
Temperature	104
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Routine	Inspection Date February 28, 2019	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 2

Observed Violations - 05 - Water level maintained, Proportional flow - gutter or skimmers versus drain

REPEAT OBSERVATION: (CORRECTED DURING INSPECTION): The skimmer to main drain flow ration is not set correctly.

CORRECTIVE ACTION(S): Readjust the flow so that only 20% comes through the main drain and 80% comes through the skimmers.

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW. (a) The flow through each skimmer shall be adjusted as often as necessary to maintain a vigorous skimming action at each skimmer. The pool water level shall be maintained at an elevation so that continuous effective surface skimming is accomplished through skimmers or over the gutter lip. For gutter pools, approximately 75% of the required recirculation flow shall be through the gutter and 25% through the main drain during normal operation. For pools with skimmers, approximately 80% of the recirculation flow shall be through skimmers and 20% through the main drain. For reverse flow pools, 100% of the required circulation shall be through the gutter or skimmer.

Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted

OBSERVATION: The maintenance number and facility addresss are not posted near the designated emergency phone.

CORRECTIVE ACTION(S): Post the emergency numbers near the designated emergency phone. Correct By: 28-Feb-2019

CODE CITATION: ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

Comments:

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge



Chris Swertfeger

Sanitarian



Doug Schaefer
(608) 785-9679