



Recreational Water Establishment Inspection Report

Establishment Information	
Facility Name CAMP DECORAH	Facility Type Outdoor Pool
Facility ID # HSAT-7QWJTR	Facility Telephone # 608 526-6418
Facility Address W7520 COUNCIL BAY RD HOLMEN , WI 54636	
Licensee Name GATEWAY AREA COUNCIL INC	Licensee Address 2600 QUARRY RD LA CROSSE , WI 54601

Pool Parameters	
Free Available Chlorine/Bromine Combined Chlorine	1.7
pH	7.4
Alkalinity	
Cyanuric Acid	
Temperature	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	

Inspection Information		
Inspection Type Routine	Inspection Date June 14, 2017	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 3

Observed Violations - 15 - Filter-aid feeders - proper concentration and chemical used, Gas chlorine.

OBSERVATION: The chemical feeder does not have flow control valves both upstream and downstream and is operated manually.

CORRECTIVE ACTION(S): Install flow control valves in compliance with ATCP 76.13(1). Correct By: 14-Jun-2017

CODE CITATION: ATCP 76.13 Disinfectant feeders and filter aid equipment. (1) GENERAL. All disinfectant feeders shall be installed according to the manufacturer's directions and used only with the disinfectant recommended by the manufacturer and meet all of the following requirements:

(a) Feeders shall be automatic, easily adjustable, capable of providing the required chemical residuals, equipped with flow control valves upstream and downstream from the feeder, easily disassembled for cleaning and maintenance, durable, and capable of accurate feeding.

Observed Violations - 13 - Approved design, data plate, intertwined with recirculation pump

OBSERVATION: The disinfectant feeder pump is not electrically connected to the recirculation pump control circuit.

CORRECTIVE ACTION(S): Electrically connect the disinfectant feeder to the recirculation pump so it cannot keep running when the recirculation pump is turned off. Correct By: 14-Jun-2017

CODE CITATION: ATCP 76.13 All disinfectant feeders shall be approved by the department of commerce and installed according to the manufacturer's directions and used only with the disinfectant recommended by the manufacturer and meet all of the following requirements:

(c) Feeder pumps shall be electrically connected to the recirculation pump control circuit and have a separate disconnect switch.

Observed Violations - 31 - General maintenance, walls, ceilings. floors, hosing spectator area separated, maintained, no hazardous conditions, adequate lighting accessibility, solid waste, garbage storage and disposal.

OBSERVATION: Stairway and ladder railings are not being maintained and repaired as necessary.

CORRECTIVE ACTION(S): Tighten railings and maintain all equipment pursuant to ATCP 76.33(1)(e). Correct By: 14-Jun-2017

CODE CITATION: ATCP 76.33 Facility maintenance, repair and sanitation. (1) POOL AREA. (e) Equipment. Pool equipment, including equipment on the deck, shall be properly located and installed and maintained and repaired as necessary.

Comments:

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge



Clark Garthwait

Sanitarian



**Doug Schaefer
(608) 785-9679**