



Recreational Water Inspection Report

| Establishment Information | |
|-----------------------------------------------------------|--------------------------------------------------------------|
| Facility Name MAYO CLINIC HEALTH SYSTEM | Facility Type Indoor Pool |
| Facility ID # HSAT-7QWATU | Facility Telephone # 608 392-5000 |
| Facility Address 191 THEATRE RD ONALASKA , WI 54650 | |
| Licensee Name MAYO CLINIC HEALTH SYSTEMS | Licensee Address 191 THEATRE RD ONALASKA , WI 54650 |

| Pool Parameters | |
|---------------------------------|---------|
| Free Available Chlorine/Bromine | 5.5 |
| Combined Chlorine | |
| Oxidation Reduction Potential | |
| Disinfectant Type | Bromine |
| Secondary Disinfectant Type | |
| Secondary Disinfectant Level | |
| pH | 7.4 |
| Alkalinity | 60 |
| Cyanuric Acid | |
| Temperature | 92 |
| Calcium Hardness | |
| Saturation Index | |
| Flowmeter Reading(s) | 250 |
| Pressure Gauges Reading(s) | 12 |
| Turnover Rate | |

| Inspection Information | | |
|-------------------------------|----------------------------------|------------------|
| Inspection Type Routine | Inspection Date March 4, 2019 | Total Time Spent |

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

| Observed Violations |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Total # 1</p> <p>Observed Violations - 14 - Disinfectant / feeders - proper concentration and chemical used. Gas chlorine. OBSERVATION: (CORRECTED DURING INSPECTION): The bromine residual was 5.5 at the time of the inspection. CORRECTIVE ACTION(S): Close the pool and raise the bromine residual to 7 before re-opening. CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (a) Minimum disinfectant residuals. Except as provided in par. (b), feeding shall result in the minimum disinfectant residuals in Table ATCP 76.14.</p> |

Comments:

VGBA inspected by MBA 3/1/19.new components installed Spring 2018. Mark the install date and life of components on MBA document.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge



Roy Eggert

Sanitarian



Doug Schaefer
(608) 785-9679