



Recreational Water Inspection Report

Establishment Information	
Facility Name AMERICINN RIVERFRONT	Facility Type Water Attraction with up to 2 Slides/Waterslides (RWT)
Facility ID # ASTS-AAWQFX	Facility Telephone # 608 769-0800
Facility Address 1835 ROSE ST LA CROSSE , WI 54603	
Licensee Name TROUTCREEK 1 LLC	Licensee Address 12554 STATE HWY 131 SOLDIERS GROVE , WI 54655

Pool Parameters	
Free Available Chlorine/Bromine	1.0
Combined Chlorine	0.6
Oxidation Reduction Potential	800
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.2
Alkalinity	90
Cyanuric Acid	
Temperature	80.6
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	175
Pressure Gauges Reading(s)	
Turnover Rate	1.8

Inspection Information		
Inspection Type Routine	Inspection Date January 23, 2020	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 5

Observed Violations - 11 - Chemicals - proper labeling and storage, no mixing of chemicals, smoking prohibited

OBSERVATION: Material safety data sheets are not available for all chemicals used in the facility.

CORRECTIVE ACTION(S): Provide material safety data sheets for all chemicals used in the facility. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.12 Labeling, storing, mixing, and handling chemicals. (4) HANDLING. (b) Material safety data sheet. Material safety data sheets shall be readily available at the pool attraction area for every chemical used.

Observed Violations - 24 - Lifeguard staffing plans - if required - approved, verified, accurate, accessible, maintained and used.

OBSERVATION: A pool basin in the facility does not have a "No Lifeguard on Duty" sign that complies with ATCP 76.22(1)(c). Letters must be at least 4 inches in height.

CORRECTIVE ACTION(S): Provide a "No Lifeguard on Duty Sign" that complies with ATCP 76.22(1)(c). Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.22 Lifeguards and Attendants. (1) LIFEGUARD AND ATTENDANT STAFFING PLANS. (c) A pool that is not required under s. ATCP 76.23 to have a lifeguard shall post a sign that states, in letters that are a minimum of 4 inches high, "No Lifeguard on Duty".

Observed Violations - 06 - Pump installed, maintained strainer baskets or screens clean, spares on hand.

OBSERVATION: A spare strainer basket or screen for the recirculation pump is not located on site.

CORRECTIVE ACTION(S): Provide a spare basket or screen. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW. (d) Strainer baskets or screens shall be continuously in use and maintained. Clean spare strainer baskets or screens shall be available. Strainer baskets for skimmers and pump strainers shall be cleaned at least daily.

Observed Violations - 33 - Pool and equipment - designed, approved, constructed, pool closed sign available, landscaping features, waterslide plunge area separated

OBSERVATION: (CORRECTED DURING INSPECTION): Palm tree in stand was placed on the required deck area near wade pool. Corrected by moving tree further than 6 feet away from water edge.

CORRECTIVE ACTION(S): Remove palm tree to a location away from the required deck area.

CODE CITATION: ATCP 76.34 Pool design. (6) Landscaping planters, pots or other plant containers may not be placed on the required deck area. Landscaping features such as bark, gravel, shrubs, or flowers may be located within the pool enclosure but shall be separated from the pool by an additional 5 feet of impervious area or maintained lawn, or the landscaping features must be installed in a 4-inch depression and the depressed area must be surrounded by a 42-inch high barrier. Landscaped areas within a pool enclosure shall be continually maintained to prevent debris from entering the water. Trees used as landscaping features may not overhang the required deck area. Sand may not be located within a pool enclosure unless the sand area is made inaccessible from the pool area by the location of a security-type barrier that is at least 42 inches high. There may be controlled entrances to the pool area if the entrances are controlled and provided with showers.

Observed Violations - 24 - Lifeguard staffing plans - if required - approved, verified, accurate, accessible, maintained and used.

OBSERVATION: No signage is posted at the whirlpool of a water attraction that is only periodically supervised.

CORRECTIVE ACTION(S): Post signage in compliance with ATCP 76.22(1)(d). "Non-guarded Area" Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.22 Lifeguards and Attendants. (1) LIFEGUARD AND ATTENDANT STAFFING PLANS. (d) A plan required under par. (a) for a whirlpool that is located in a water attraction complex shall specify that at least one attendant shall provide periodic supervision. If a whirlpool is not supervised by an attendant at all times, a sign shall be posted that states in letters at least 4 inches high: "Non-guarded area."

Comments:

[AR to send list of upcoming CPO classes](#)

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Dale Rozmenoski



Amanda Ramos
(608) 785-9771



Recreational Water Inspection Report

Establishment Information	
Facility Name AMERICINN RIVERFRONT	Facility Type Additional Indoor Pool
Facility ID # ASTS-AAWQFP	Facility Telephone # 608 769-0800
Facility Address 1835 ROSE ST LA CROSSE , WI 54603	
Licensee Name TROUTCREEK 1 LLC	Licensee Address 12554 STATE HWY 131 SOLDIERS GROVE , WI 54655

Pool Parameters	
Free Available Chlorine/Bromine	1.6
Combined Chlorine	0.8
Oxidation Reduction Potential	790
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.2
Alkalinity	30
Cyanuric Acid	
Temperature	82.4
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	60
Pressure Gauges Reading(s)	
Turnover Rate	1.2

Inspection Information		
Inspection Type Routine	Inspection Date January 23, 2020	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 3

Observed Violations - 13 - Approved design, data plate, intertwined with recirculation pump

OBSERVATION: The disinfectant feeder pump is not electrically connected to the recirculation pump control circuit.

CORRECTIVE ACTION(S): Electrically connect the disinfectant feeder to the recirculation pump so it cannot keep running when the recirculation pump is turned off. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.13 All disinfectant feeders shall be approved by the department of commerce and installed according to the manufacturer's directions and used only with the disinfectant recommended by the manufacturer and meet all of the following requirements:

(c) Feeder pumps shall be electrically connected to the recirculation pump control circuit and have a separate disconnect switch.

Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.

OBSERVATION: The total alkalinity is 30.

CORRECTIVE ACTION(S): Maintain the total alkalinity between 60 and 180 ppm. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (d) Alkalinity. The total alkalinity of pool water shall be maintained between 60 and 180 ppm as calcium carbonate unless it can be shown that another level of total alkalinity produces chemically balanced water based on calculations approved by the department.

Observed Violations - 14 - Disinfectant / feeders - proper concentration and chemical used. Gas chlorine.

OBSERVATION: The chlorine residual was 1.6 at the time of the inspection.

CORRECTIVE ACTION(S): Close the pool and raise the chlorine residual to 2.0 before re-opening. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (a) Minimum disinfectant residuals. Except as provided in par. (b), feeding shall result in the minimum disinfectant residuals in Table ATCP 76.14.

Comments:

Wade Pool

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Dale Rozmenoski



**Amanda Ramos
(608) 785-9771**



Recreational Water Inspection Report

Establishment Information	
Facility Name AMERICINN RIVERFRONT	Facility Type Additional Indoor Pool
Facility ID # ASTS-AAWQFF	Facility Telephone # 608 769-0800
Facility Address 1835 ROSE ST LA CROSSE , WI 54603	
Licensee Name TROUTCREEK 1 LLC	Licensee Address 12554 STATE HWY 131 SOLDIERS GROVE , WI 54655

Pool Parameters	
Free Available Chlorine/Bromine	4.8
Combined Chlorine	2.4
Oxidation Reduction Potential	695
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.0
Alkalinity	30
Cyanuric Acid	
Temperature	101.5
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	40
Pressure Gauges Reading(s)	
Turnover Rate	.86

Inspection Information		
Inspection Type Routine	Inspection Date January 23, 2020	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 4

Observed Violations - 08 - Recirculation rate-turnover

OBSERVATION: The whirlpool has a maximum turnover rate of greater than 30 minutes.

CORRECTIVE ACTION(S): Immediately adjust or repair the equipment to operate at a proper turnover rate. Correct By: 30-Jan-2020

CODE CITATION: ATCP 76.11 Recirculation system. (4) PUMPS. The pump manufacturer's maintenance and operating instructions shall be followed. Recirculation pumps shall continuously achieve the designed pool water recirculation rate except during maintenance operations. The turnover time for pools shall be as follows: (d) Whirlpools. The maximum turnover time for a whirlpool shall be 30 minutes.

Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.

OBSERVATION: The pH is 7.0.

CORRECTIVE ACTION(S): Close the pool and do not reopen it until the pH falls between 7.2 and 7.8. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (a) Minimum disinfectant residuals. Except as provided in par. (b), feeding shall result in the minimum disinfectant residuals in Table ATCP 76.14.

(c) pH control. The water's pH shall be maintained within a range of 7.2 to 7.8.

Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.

OBSERVATION: The total alkalinity is 30.

CORRECTIVE ACTION(S): Maintain the total alkalinity between 60 and 180 ppm. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (d) Alkalinity. The total alkalinity of pool water shall be maintained between 60 and 180 ppm as calcium carbonate unless it can be shown that another level of total alkalinity produces chemically balanced water based on calculations approved by the department.

Observed Violations - 16 - pH alkalinity within limits or balanced, Cyanuric acid - within limits, Superoxidation - done as needed.

REPEAT OBSERVATION: The combined chlorine is 2.4.

CORRECTIVE ACTION(S): Treat the pool with breakpoint chlorination using a chlorine product or a nonchlorinated oxidizer. Correct By: 23-Jan-2020

CODE CITATION: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (e) Combined chlorine. When combined chlorine exceeds 0.5 ppm in an outdoor pool or 0.8 ppm in an indoor pool, the water shall be treated to breakpoint chlorination using a chlorine product or a nonchlorinated oxidizer such as potassium peroxydisulfate. Isocyanurates may not be used to reach breakpoint chlorination. The pool shall be closed to the public during periods of breakpoint chlorination when a chlorine product is used.

Comments:

Whirl pool

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Dale Rozmenoski



Amanda Ramos
(608) 785-9771