



Recreational Water Inspection Report

Establishment Information	
Facility Name LA CROSSE COUNTRY CLUB	Facility Type Outdoor Pool
Facility ID # HSAT-7QWEY8	Facility Telephone # 608 781-5837
Facility Address 300 MARCOU ONALASKA , WI 54650	
Licensee Name LA CROSSE COUNTRY CLUB	Licensee Address 300 MARCOU RD ONALASKA , WI 54650

Pool Parameters	
Free Available Chlorine/Bromine	6.2
Combined Chlorine	0
Oxidation Reduction Potential	
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.6
Alkalinity	70
Cyanuric Acid	
Temperature	83
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	700
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Routine	Inspection Date August 7, 2019	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 7</p> <p>Observed Violations - 21 - Plumbing air-gaps, cross-connections, maintained, installed piping coded or labeled OBSERVATION: (CORRECTED DURING INSPECTION): The potable water supply line is below the overflow point of the receiving basin. A hose was also in the same fill piping. CORRECTIVE ACTION(S): Install a proper air gap or a reduced pressure zone backflow assembly on the water supply line. CODE CITATION: ATCP 76.19 Water supply and temperature. (1) WATER SUPPLY PROTECTION. A minimum air-gap of 2 pipe diameters or 6 inches, whichever is less, shall exist between the potable water supply inlet and the overflow point of any pool, makeup tank, surge tank, solution tank, or slurry tank unless another department-approved backflow and backsiphonage prevention device is provided.</p> <p>Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located,</p>

good condition, phone numbers posted

OBSERVATION: (CORRECTED DURING INSPECTION): There is no posted maximum patron load.

CORRECTIVE ACTION(S): Calculate and post the maximum patron load in compliance with ATCP 76.25(1).

CODE CITATION: ATCP 76.25 Permissible patron load. (1) WATER ATTRACTIONS. The maximum number of patrons permitted to be in an individual water attraction at any one time shall be calculated on the basis of allowing one patron for every 15 square feet of water surface area. The splash zone of any water attraction shall be included in the calculation of the water surface.

Observed Violations - 06 - Pump installed, maintained strainer baskets or screens clean, spares on hand.

OBSERVATION: A spare strainer basket or screen for the large pool recirculation pump is not located on site.

CORRECTIVE ACTION(S): Provide a spare basket or screen. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW. (d) Strainer baskets or screens shall be continuously in use and maintained. Clean spare strainer baskets or screens shall be available. Strainer baskets for skimmers and pump strainers shall be cleaned at least daily.

Observed Violations - 24 - Lifeguard staffing plans - if required - approved, verified, accurate, accessible, maintained and used.

OBSERVATION: The facility does not have a lifeguard staffing plan.

CORRECTIVE ACTION(S): Create a written plan pursuant to the requirements of ATCP 76.22 and submit it for approval. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.22 Lifeguards and Attendants. (1) LIFEGUARD AND ATTENDANT STAFFING PLANS. (a) The owner or operator of a pool, including a whirlpool over 4 feet deep and a pool with a visual obstruction, and the owner or operator of a water attraction or water attraction complex shall submit a written, proposed lifeguard and attendant staffing plan to the department or the department's agent for approval. The owner or operator shall keep a copy of the plan at the pool. The plan shall include all of the following:

1. The square footage of the pool, water attraction, and water attraction complex as applicable.
2. The maximum and average patron load.
3. The hours of operation.
4. The location of each lifeguard station and each first aid station.
5. The number of lifeguards or attendants on duty pursuant to ATCP 76.23.
6. A diagram of the facility that indicates the placement of attendants, lifeguards, chairs and stations for both average and maximum patron capacity. The diagram shall include each obstruction.
7. A method of communication when 2 or more attendants or lifeguards are required for a water attraction.

Observed Violations - 24 - Lifeguard staffing plans - if required - approved, verified, accurate, accessible, maintained and used.

OBSERVATION: There are no lifeguards present during the morning adult lap swim.

CORRECTIVE ACTION(S): The facility must remain closed when lifeguards are not present and not in compliance with ATCP 76.23(1). Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.23 Lifeguard and attendant placement and staffing requirements. (1) GENERAL. (a) 1. Each pool having a surface area of 2,000 square feet or more shall be staffed pursuant to Table ATCP 76.23-A and Table ATCP 76.23-B when the pool is in use or is open to the public. If the requirements in Table ATCP 76.23-A and Table ATCP 76.32-B conflict, the pool shall comply with the strictest requirements of Table ATCP 76.23-A or Table ATCP 76.23-B.

2. An operator may close a portion of a pool to patrons in order to meet the square footage limits in Table ATCP 76.23-A for lifeguard staffing, except that lifeguard staffing requirements for a pool of 2,000 to 4,999 square feet shall be maintained.

3. When the patron load of a pool exceeds 336 patrons, one lifeguard shall be provided for each additional 100 patrons or fraction thereof.

(b) A pool type that is not addressed in Table ATCP 76.23-A or ATCP 76.23-B shall request evaluation by the department and follow the requirements specified by the department following the evaluation.

(c) An additional lifeguard shall be provided for every 2 slide flumes installed at a pool other than a separate waterslide plunge pool.

(d) An attendant responsible for enforcing waterslide usage rules shall be stationed at the entrance to the waterslide flume.

Observed Violations - 34 - Security - pool enclosure, controlled access, self-closing gates and latches access through bathhouse fencing safety rope as required.

OBSERVATION: The door or gate to the pool enclosure is not self-closing or latching.

CORRECTIVE ACTION(S): Repair the door immediately so that it is self-closing and latching. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.34 Pool design. (4) All pool areas shall be enclosed and have self-closing and latching gates or doors that are lockable.

Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted

OBSERVATION: The non-emergency phone number is not posted. The pool address is not posted.

CORRECTIVE ACTION(S): Post the non-emergency number and pool address near the designated emergency phone. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

Comments:

Post the permit in the guard area where it can be seen when the window is up.

Make the DSPS approval letter available for inspection of the VBGA and installation dates and life spans of all grates.

Reinspection 8/30/19, fee applies.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge



Joe Bushmaker

Sanitarian



Doug Schaefer
(608) 785-9679



Recreational Water Inspection Report

Establishment Information	
Facility Name LA CROSSE COUNTRY CLUB	Facility Type Additional Outdoor Pool
Facility ID # HSAT-7QX2K4	Facility Telephone # 608 781-5837
Facility Address 300 MARCOU RD ONALASKA , WI 54650	
Licensee Name LA CROSSE COUNTRY CLUB	Licensee Address 300 MARCOU RD ONALASKA , WI 54650

Pool Parameters	
Free Available Chlorine/Bromine	6.6
Combined Chlorine	0
Oxidation Reduction Potential	
Disinfectant Type	Chlorine-Liquid
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.4
Alkalinity	90
Cyanuric Acid	
Temperature	83
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	140
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Routine	Inspection Date August 7, 2019	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations

Total # 3

Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted

OBSERVATION: (CORRECTED DURING INSPECTION): There is no posted maximum patron load.

CORRECTIVE ACTION(S): Calculate and post the maximum patron load in compliance with ATCP 76.25(2). Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.25 Permissible patron load. (2) POOLS. (a) Pools used for swimming and combination pools. The maximum number of patrons permitted to be in the water of a pool used for swimming or a combination pool at any one time shall be computed on the basis of allowing one patron for every 15 square feet of the shallow portion of the pool and one patron for every 25 square feet of the deep portion of the pool. Three hundred square feet of pool water surface around each diving board and platform may be excluded in computing the permissible patron load. An additional 10 patrons for each diving board shall be included in the computation.

Observed Violations - 34 - Security - pool enclosure, controlled access, self-closing gates and latches access through bathhouse fencing safety rope as required.

OBSERVATION: The door or gate to the pool enclosure is not self-closing or latching.

CORRECTIVE ACTION(S): Repair the door immediately so that it is self-closing and latching. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.34 Pool design. (4) All pool areas shall be enclosed and have self-closing and latching gates or doors that are lockable.

Observed Violations - 26 - Permissible patron load, Rescue equipment, first aid equipment, telephone present, located, good condition, phone numbers posted

OBSERVATION: The non-emergency number and pool address are not posted near the designated emergency phone.

CORRECTIVE ACTION(S): Post the non-emergency number and address near the designated emergency phone. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

Comments:

Post the permit in the guard area where it is visible when the window is up.

Make the DSPS approval letter available for inspection of the VGBA and installation dates and life spans of grates.

Reinspection 8/30/19, fee applies.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Joe Bushmaker



Doug Schaefer
(608) 785-9679



Recreational Water Inspection Report

Establishment Information	
Facility Name LA CROSSE COUNTRY CLUB	Facility Type Additional Outdoor Pool
Facility ID # HSAT-7QX2K4	Facility Telephone # 608 781-5837
Facility Address 300 MARCOU RD ONALASKA , WI 54650	
Licensee Name LA CROSSE COUNTRY CLUB	Licensee Address 300 MARCOU RD ONALASKA , WI 54650

Pool Parameters	
Free Available Chlorine/Bromine	
Combined Chlorine	
Oxidation Reduction Potential	
Disinfectant Type	
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	
Alkalinity	
Cyanuric Acid	
Temperature	
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Re-inspection	Inspection Date August 30, 2019	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 1</p> <p>Observed Violations - 34 - Security - pool enclosure, controlled access, self-closing gates and latches access through bathhouse fencing safety rope as required.</p> <p>REPEAT OBSERVATION: The door or gate to the pool enclosure is not self-closing or latching.</p> <p>CORRECTIVE ACTION(S): Repair the door immediately so that it is self-closing and latching. Correct By: 07-Aug-2019</p> <p>CODE CITATION: ATCP 76.34 Pool design. (4) All pool areas shall be enclosed and have self-closing and latching gates or doors that are lockable.</p>

Corrected Hazards

The following hazard(s) have been corrected since the last inspection.

Total # 1

[C] ATCP 76.26(2) - EMERGENCY CONTACT PHONE NUMBERS NOT POSTED

OBSERVATION: The non-emergency number and pool address are not posted near the designated emergency phone.

CORRECTIVE ACTION(S): Post the non-emergency number and address near the designated emergency phone. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

Comments:

Pool is closing for the season Monday.

Entry gate must be self closing and latching at the start of the 2020 season.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Joe Bushmaster



Doug Schaefer
(608) 785-9679



Recreational Water Inspection Report

Establishment Information	
Facility Name LA CROSSE COUNTRY CLUB	Facility Type Outdoor Pool
Facility ID # HSAT-7QWEY8	Facility Telephone # 608 781-5837
Facility Address 300 MARCOU ONALASKA , WI 54650	
Licensee Name LA CROSSE COUNTRY CLUB	Licensee Address 300 MARCOU RD ONALASKA , WI 54650

Pool Parameters	
Free Available Chlorine/Bromine	
Combined Chlorine	
Oxidation Reduction Potential	
Disinfectant Type	
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	
Alkalinity	
Cyanuric Acid	
Temperature	
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Re-inspection	Inspection Date August 30, 2019	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 1</p> <p>Observed Violations - 34 - Security - pool enclosure, controlled access, self-closing gates and latches access through bathhouse fencing safety rope as required.</p> <p>REPEAT OBSERVATION: The door or gate to the pool enclosure is not self-closing or latching. 8/30/19 gate blocked open with pin. Gate does not self close and latch.</p> <p>CORRECTIVE ACTION(S): Repair the door immediately so that it is self-closing and latching. Correct By: 07-Aug-2019</p> <p>CODE CITATION: ATCP 76.34 Pool design. (4) All pool areas shall be enclosed and have self-closing and latching gates or doors that are lockable.</p>

Corrected Hazards

The following hazard(s) have been corrected since the last inspection.

Total # 4

[A] ATCP 76.11(2)(d) - SPARE STRAINER BASKET - REQUIREMENT

OBSERVATION: A spare strainer basket or screen for the large pool recirculation pump is not located on site.

CORRECTIVE ACTION(S): Provide a spare basket or screen. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.11 Recirculation system. (2) SKIMMERS AND RECIRCULATION FLOW. (d) Strainer baskets or screens shall be continuously in use and maintained. Clean spare strainer baskets or screens shall be available. Strainer baskets for skimmers and pump strainers shall be cleaned at least daily.

[A] ATCP 76.22(1)(a) - LIFEGUARD AND ATTENDANT STAFFING PLAN

OBSERVATION: The facility does not have a lifeguard staffing plan.

CORRECTIVE ACTION(S): Create a written plan pursuant to the requirements of ATCP 76.22 and submit it for approval. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.22 Lifeguards and Attendants. (1) LIFEGUARD AND ATTENDANT STAFFING PLANS. (a) The owner or operator of a pool, including a whirlpool over 4 feet deep and a pool with a visual obstruction, and the owner or operator of a water attraction or water attraction complex shall submit a written, proposed lifeguard and attendant staffing plan to the department or the department's agent for approval. The owner or operator shall keep a copy of the plan at the pool. The plan shall include all of the following:

1. The square footage of the pool, water attraction, and water attraction complex as applicable.
2. The maximum and average patron load.
3. The hours of operation.
4. The location of each lifeguard station and each first aid station.
5. The number of lifeguards or attendants on duty pursuant to ATCP 76.23.
6. A diagram of the facility that indicates the placement of attendants, lifeguards, chairs and stations for both average and maximum patron capacity. The diagram shall include each obstruction.
7. A method of communication when 2 or more attendants or lifeguards are required for a water attraction.

[A] ATCP 76.23(1) - LIFEGUARD STAFFING INADEQUATE

OBSERVATION: There are no lifeguards present during the morning adult lap swim.

CORRECTIVE ACTION(S): The facility must remain closed when lifeguards are not present and not in compliance with ATCP 76.23(1). Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.23 Lifeguard and attendant placement and staffing requirements. (1) GENERAL. (a) 1. Each pool having a surface area of 2,000 square feet or more shall be staffed pursuant to Table ATCP 76.23-A and Table ATCP 76.23-B when the pool is in use or is open to the public. If the requirements in Table ATCP 76.23-A and Table ATCP 76.32-B conflict, the pool shall comply with the strictest requirements of Table ATCP 76.23-A or Table ATCP 76.23-B.

2. An operator may close a portion of a pool to patrons in order to meet the square footage limits in Table ATCP 76.23-A for lifeguard staffing, except that lifeguard staffing requirements for a pool of 2,000 to 4,999 square feet shall be maintained.

3. When the patron load of a pool exceeds 336 patrons, one lifeguard shall be provided for each additional 100 patrons or fraction thereof.

(b) A pool type that is not addressed in Table ATCP 76.23-A or ATCP 76.23-B shall request evaluation by the department and follow the requirements specified by the department following the evaluation.

(c) An additional lifeguard shall be provided for every 2 slide flumes installed at a pool other than a separate waterslide plunge pool.

(d) An attendant responsible for enforcing waterslide usage rules shall be stationed at the entrance to the waterslide flume.

[C] ATCP 76.26(2) - EMERGENCY CONTACT PHONE NUMBERS NOT POSTED

OBSERVATION: The non-emergency phone number is not posted. The pool address is not posted.

CORRECTIVE ACTION(S): Post the non-emergency number and pool address near the designated emergency phone. Correct By: 07-Aug-2019

CODE CITATION: ATCP 76.26 Rescue equipment. (2) TELEPHONE. For outdoor pools, a working telephone shall be available in the pool area. For indoor pools, a working telephone shall be available within the enclosed area around a pool. A current list of emergency numbers and the facility's location shall be attached to or posted near the telephone. Cellular or cordless phones may not be used to comply with this subsection.

Note: A request for an alternative location for a telephone or another system of communication that provides access to emergency service during hours of pool operation may be made under s. ATCP 76.02 (2).

Comments:

Pool is closing for the season Monday.

Gate must be self closing and latching at the start of the 2020 season.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in ch.227 statute, if state licensed, or a local ordinance if licensed by an agent health department.

Person in Charge

Sanitarian



Joe Bushmaster



Doug Schaefer
(608) 785-9679